

10	12/26/2019	ND	ND	ND	ND	ND	ND	ND	5.2	
10	1/8/2020	ND	ND	ND	ND	ND	ND	ND	6.4	
10	1/22/2020	ND	ND	ND	ND	ND	ND	ND	6.5	
10	2/4/2020	ND	ND	ND	ND	ND	ND	ND	5.4	
10	2/17/2020	ND	ND	ND	ND	ND	ND	ND	7.2	
10	3/18/2020	ND	ND	ND	ND	ND	ND	ND	ND	Well out-of-service 2/24/2020 to 3/10/2020 for installation of 3rd ion exchange vessel
10	3/31/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	4/14/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	4/28/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	5/13/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	5/27/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	6/10/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	6/24/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	7/1/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	7/15/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	8/5/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	8/18/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	9/2/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	9/16/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	10/7/2020	ND	ND	ND	ND	ND	ND	ND	2.6	
10	10/21/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	11/4/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	11/18/2020	ND	ND	ND	ND	ND	ND	ND	ND	
10	12/2/2020	ND	ND	ND	ND	ND	ND	ND	3.9	
10	12/15/2020	ND	ND	ND	ND	ND	ND	ND	3.7	
10	1/6/2021	ND	ND	ND	ND	ND	ND	3.0	5.8	
10	1/20/2021	ND	ND	ND	ND	ND	ND	ND	5.9	Removed from service on 1/29/2021

